

附件一：涉及产品型号及批号

产品型号	产品批号	备注
04.607.402	2L33452, 2L33456, 2L40723, 2L40728, 2L71755, 2L71758, 2L71759, 2L79940, 2L80405, 2L80407, 3L06928, 3L06929, 3L06930, 3L08450, 3L08452, 3L08454, 3L08456, 3L15899	我司有进口 有销售
	2L71760, 2L79941, 2L80404, 2L80406, 2L80408, 2L80409, 2L80410, 2L80411, 2L80412, 2L91858, 3L15897, 3L15900, 3L15902, 3L15903, 3L15904, 3L15915, 3L15923, 3L15927, 3L24559, 3L26702, 3L26703, 3L28898, 3L28901, 3L28907, 3L28910, 3L28913, 3L28916, 3L37334, 3L38172, 3L38173, 3L38177, 3L59044, 3L59046, 3L59048, 3L69189, 3L93647, 3L93948, 4L12495, 4L12515, 4L12530, 4L15295, 4L15297, 4L15298, 4L22644, 4L22645, 4L22646, 4L44336, 4L44338, 4L49656, 4L49663, 4L57557, 4L66081, 4L66084, 4L66086, 4L84351, 4L86152, 5L15679, 5L15714, 5L15717, 5L15721, 5L23579	我司有进口 未销售
	2L33453, 2L33454, 2L33455, 2L40721, 2L40726, 2L49034, 2L51832, 2L68992, 2L69276, 2L71756, 2L71757, 3L08448, 3L15896, 3L15898, 3L15913, 3L15925, 3L15929, 3L24895, 3L28918, 3L93646, 3L93947, 3L93949, 4L12517, 4L12534, 4L15296, 4L15299, 4L31959, 4L49661, 4L57553, 4L75574, 5L02812, 5L15682, 5L15718, 5L15719, 5L23581, 5L23582, 5L23583, 5L35404	我司无进口
04.607.402S	2L33799, 2L36789, 2L43711, 2L54942, 2L63125, 2L86917, 2L94099, 3L38612, 3L41799, 3L50599, 3L53014, 3L59638, 3L88502, 4L56205, 4L63893, 4L63915, 4L63961, 5L09577, 5L37753, 5L44576, 5L48010, 5L52249	我司无进口



注：此次召回仅限上述表格中产品型号及批号，强生其余产品不受此次召回影响。

--结束--

强生(中国)医疗器械有限公司  
**Johnson & Johnson Medical (China) Ltd.**  
 强生(上海)医疗器械有限公司  
**Johnson & Johnson Medical (Shanghai) Ltd.**